

Type	Hits	Ref	Search Text	DBs	Time Stamp
BRS	249	S1	bear\$3 near diagnos\$3	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	6/7/06
BRS	0	S2	(bear\$3 near diagnos\$3) and railway and axle and calculat\$3 and feedback	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	6/7/06
BRS	1	S3	(bear\$3 near diagnos\$3) and railway and axle and calculat\$3	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	6/7/06
BRS	5	S4	(bear\$3 near diagnos\$3) and railway	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	6/7/06
BRS	88	S5	bearing near diagnostic	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	6/7/06
BRS	16	S6	S5 and electrical	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	6/7/06
BRS	9	S7	S6 and sensor	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	6/7/06
BRS	1306	S8	(384/448 or 384/91 or 384/8 or 384/7 or 384/594 or 384/595).ccls.	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	6/7/06
BRS	2447	S9	(73/602 or 702/35 or 702/34 or 702/183).ccls.	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	6/7/06
BRS	40	S10	(246/169).ccls.	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	6/7/06
BRS	3792	S11	S8 or S9 or S10	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	6/7/06
BRS	1330	S12	S11 and bear\$3	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	6/7/06
BRS	33	S13	S12 and (electric\$2 near sensor\$1)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	6/7/06
BRS	23	S14	S13 and process\$3	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	6/7/06
BRS	20	S15	S14 and control\$4	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	6/7/06
BRS	17	S16	S15 and signal and unit	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	6/7/06
BRS	1	S17	S16 and (feed near back)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	6/7/06
BRS	48	S18	(US-6047674-\$ or US-6085706-\$ or US-5802981-\$ or US-4353309-\$ or US-5263461-\$ or US-5269277-\$ or US-5295444-\$ or US-5301111-\$ or US-5373823-\$ or US-5619976-\$ or US-5621326-\$ or US-6154970-\$ or US-6219600-\$ or US-4300454-\$ or US-4776283-\$ or US-4843557-\$ or US-4986191-\$ or US-4999779-\$ or US-5000096-\$ or US-5290095-\$ or US-5498072-\$ or US-5506772-\$ or US-5811683-\$ or US-5842589-\$ or US-6178947-\$ or US-6211681-\$).did. or (US-6236954-\$ or US-6247413-\$ or US-3924460-\$ or US-3911827-\$ or US-3799632-\$ or US-3785298-\$ or US-4162653-\$ or US-4067261-\$ or US-4067262-\$ or US-4072371-\$ or US-4265492-\$ or US-4285280-\$ or US-4290509-\$ or US-4304377-\$ or US-4308800-\$ or US-4316418-\$ or US-4332201-\$ or US-4360084-\$ or US-4367673-\$ or US-4373446-\$ or US-4381713-\$ or US-4416203-\$).did.	USPAT	6/8/06
BRS	31	S19	S18 and bear\$3	USPAT	6/8/06
BRS	1	S20	S19 and (feedback or (feed near back))	USPAT	6/8/06
BRS	1	S22	S21 and ((abnormality or defect or service) near bearing)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	10/28/06
IS&R	4	S23	((("6199018") or ("20050259903"))).PN.	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	10/28/06
BRS	48	S24	(US-6219600-\$ or US-4843557-\$ or US-4776283-\$ or US-4416203-\$ or US-4381713-\$ or US-4300454-\$ or US-4290509-\$ or US-4285280-\$ or US-5621326-\$ or US-5619976-\$ or US-5506772-\$ or US-5498072-\$ or US-6236954-\$ or US-4265492-\$ or US-4162653-\$ or US-4072371-\$ or US-4067262-\$ or US-6247413-\$ or US-5373823-\$ or US-5301111-\$ or US-5295444-\$ or US-5290095-\$ or US-4373446-\$ or US-4367673-\$ or US-4360084-\$ or US-4353309-\$).did. or (US-6047674-\$ or US-5842589-\$ or US-5811683-\$ or US-5802981-\$ or US-4067261-\$ or US-3924460-\$ or US-3911827-\$ or US-6211681-\$ or US-6178947-\$ or US-6154970-\$ or US-6085706-\$ or US-5269277-\$ or US-5263461-\$ or US-5000096-\$ or US-4999779-\$ or US-4986191-\$ or US-3799632-\$ or US-3785298-\$ or US-4332201-\$ or US-4316418-\$ or US-4308800-\$ or US-4304377-\$).did.	USPAT	10/28/06
BRS	32	S27	bearing near abnormality	USPAT	10/28/06
BRS	0	S25	S24 and S22	USPAT	10/28/06
BRS	0	S26	S24 and abnormality	USPAT	10/28/06
BRS	24	S28	S27 and sens\$3	USPAT	10/28/06
BRS	0	S29	S28 and feedback	USPAT	10/28/06
BRS	13	S30	S28 and control	USPAT	10/28/06
BRS	2	S31	S27 and (railway or train or metro or subway)	USPAT	10/28/06
BRS	168	S21	(246/169A).ccls.	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	10/28/06